

Errata for VIRM: In-service certification (WoF and CoF) , version3, amendment 4, November 2008

Please note the following corrections in the VIRM and keep this page in the front of your manual, or print out the corrected pages from the NZTA website www.landtransport.govt.nz/certifiers. Make sure you print from the correct manual.

Introduction page 5-3: In the table under running gear, read the following for a) and f):

- a) Two-post vehicle hoist and industrial quality trolley jack
- f) Industrial quality trolley jack and four axle stands

General Vehicle page 8-1-4, RfRs 27.a) and 28.a) to read the following:

27.a) is knotted, frayed or excessively corroded, or

28.a) is excessively corroded, or

General Vehicle page 10-1-1, under RfRs 3 and 6, the references to Note 2 should be to Note 3.

General Vehicle page 3-1-4, Figure 3-1-2: the frontal structure (radiator support panel etc) should be shaded, as below:

